

PERFORMA FOR THE SAFETY OF THE SCHOOL BUILDING

PART-1

(To be filled by the Head of the School/Instruction)

1. Name of the School : KMV Collegiate Sr. Sec. School, Jalandhar
2. Location : Tanda Road, Jalandhar.
3. Plot Area : 46478.80 Sq. Ft.
4. Plinth Area : 25117.92 Sq. Ft.
5. No. of Storeys : Double Story Partly Single
6. Year of Construction of the building : 1980
7. If the building has been constructed under the supervision of the qualified engineer, the following details may be given : Sh. Surjit Singh 3 years Diploma in Civil Engineering
Name of the engineer with qualification : Civil Engineering
(a) Address of the engineer : 35/36, Gian Nagar, Jalandhar
(b) Set of the structural drawing used in Construction is available : N.A.
(c) Name & address of the architect : Mr. B.K. Singhal, Shastri Market, Jalandhar, B.Arch (RKE) A.I.I.A., F.I.R.A. Regd. No. CA/75/172
8. Whether the building has been constructed For the purpose of
(a) School : Yes/No
(b) Residential purpose & converted for use as a school : Yes/No ✓
9. Material used for roofs
(a) R. C. C. slabe : Yes/No ✓
(b) R. S. Jolsts and battons : Yes/No ✓
(c) Wooden joists and battons : Yes/No ✓
10. Matrial used for walls
(a) Mud Morter : Yes/No
(b) Cement morter : Yes/No
(c) Plaster i) Lime Morter : Yes/No
ii) Cement Morter : Yes/No ✓
11. Flooring
(a) Conglomerate : Yes/No
(b) Terrazo : Yes/No ✓
(c) Brick faving : Yes/No ✓
12. A detailed drawing indicating dimintions of the rooms alongwith size and location of doors and windows (attached) : -----ATTACHED-----

Principal Signature Stamp of the
K.M.V. Collegiate Sr. Sec. School
Jalandhar City Jalandhar City.

K.M.V. Collegiate Sr. Sec. School, Jalandhar

PART-II

(To be filled by the S.D.O. of the P.W.D., B&R, Department)

- (a) I have visited the above mentioned School on 01-10-2020 and have visually inspection it from all angle of safety and I find it fit for normal use as a School Buildings.
- (b) In case any addition/alteration or expansion and modification of this building is to be carried out, the same be carried out under the supervision of technically qualified Engineer and this certificate may again be obtained after the completion from the under signed.
- (c) In case the building is effected by flood, or if there is settlement of walls / foundation or sagating of roofs etc. Immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- (d) This building can be safety occupied for normal use upto (indicate year upto which it can be used) for 31/3/2021 [March 2020 to March] 2021 This school Building is visually safe.

Executive Engineer
Provincial Divn. PWD B&R Br.
Jalandhar Cantt

Signature Stamp of the
Head office of the School
Jalandhar City.

Ref. No. 1383
Jalandhar.

Dated: 19-10-2020